



FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN END FOR BOWL

PROTECT YOUR ENGINE FROM WATER DAMAGE

In a modern fuel system, water can cause just as much damage as dirt. It leads to rust and corrosion which not only harms the tank, but also is passed along in the fuel stream in the form of hard particulate which causes engine wear. Combined with heat and pressure, water can damage parts through cavitation, erosion, etching and spalling.


Baldwin Fuel/Water Separators can help prevent damage by efficiently removing water from fuel before it reaches your engine.



FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN PORT FOR BOWL

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF791-O 	Quicksilver Outboard Applications	Racor S3213	Thread: 11/16-16 O.D.: 3 25/32 (96.0) Length: 4 1/32 (102.4) F. Gskt.: 2 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/4-10
BF1204-O 	Racor 225R Assembly	Racor R26S	Thread: 1-14 O.D.: 3 3/4 (95.3) Length: 4 11/16 (119.1) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 1 1/4-10, Integral Post Seal Related To: BF1204 (Drain Version); BF1204-SP (Sensor Port Version)
BF1222-O 	Ford Engines	Ford F2TZ-9N-184-A; Motorcraft FD3375	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 4 1/8 (104.8) A. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3-12, Integral Post Seal Related To: BF1222 (Drain Version) BF1222-SP (Sensor Port Version)
BF1223-O 	Ford Trucks	Ford F1HZ-9365-A; Motorcraft FD3368	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 5 7/32 (132.6) A. Gskt.: 1 Included F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10, Integral Post Seal Related To: BF1223 (Drain Version) BF1223-SP (Sensor Port Version)
BF1249-O 	Blue Bird, Ford, Freightliner, International Buses, Trucks; Hamm Rollers; Hyundai, Liebherr Equipment; Optional on Cummins Engines	Nissan FL6442N	Thread: 1-14 O.D.: 3 21/32 (92.9) Length: 6 5/8 (168.3) I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 1 1/4-10, Integral Post Seal Related To: BF1249 (Drain Version) BF1249-SP (Sensor Port Version) CAUTION: Furnished O-Ring must be installed on Post for Seal.
BF1278-O 	Ingersoll Rand Compressors	Ingersoll Rand 54468178	Thread: 1-12 O.D.: 3 11/16 (93.7) Length: 4 1/8 (104.8) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: M80 x 2.5, Integral Post Seal Related To: BF1278 (Drain Version)













FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN PORT FOR BOWL

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF1281-O 	Primary Fuel for Racor 4120 Fuel Assembly Series	Racor R120P; Donaldson P550177; Fleetguard FS19754	Thread: 1-14 O.D.: 4 13/32 (111.9) Length: 8 19/32 (218.3) A. Gskt.: 1 Included F. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal Related To: BF1281 (Drain Version)
BF1282-O 	Agco, Komatsu Equipment; Case Dump Trucks; Cummins Engines	Fleetguard FS1241	Thread: 1-14 O.D.: 3 21/32 (92.9) Length: 4 19/32 (116.7) F. Gskt.: 1 Included I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 1 1/4-2B Related To: BF1282 (Drain Version) CAUTION: Furnished D-Ring must be installed on post for seal.
BF1283-O 	Caterpillar Equipment, Industrial, Marine, Truck Engines; Racor 4120 Fuel Assembly Series	Racor R120S; Donaldson P550175; Fleetguard FS1071	Thread: 1-14 O.D.: 4 13/32 (111.9) Length: 8 19/32 (218.3) A. Gskt.: 1 Included F. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal Related To: BF1283 (Drain Version), BF1283-SP (Sensor Port Version)
BF1287-O 	Komatsu HD465-7, HD605-7 Dump Trucks	Komatsu 600-311-3210, 600-319-3240	Thread: 1 1/4-12 O.D.: 4 7/8 (123.8) Length: 9 29/32 (251.6) F. Gskt.: 1 Included F. Gskt.: 1 Included	Contains: Bowl Thread: M85 x 2.5, Integral Post Seal Related To: BF1357 (Drain Version)
BF1288-O 	Komatsu Dump Trucks, Equipment	Komatsu 600-311-4510, 600-319-4500	Thread: 1 1/4-12 O.D.: 4 7/8 (123.8) Length: 9 29/32 (251.6) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal Related To: BF1357 (Drain Version)
BF1292-O 	Deutz Engines; Deutz-Fahr, Fendt Tractors; Iveco Trucks	Deutz 4291642; Fendt F339202060120; Iveco 42549295; Mercedes-Benz 4771602, A0004771602; Racor R90T-DMAX	Thread: 1-14 O.D.: 4 5/32 (105.6) Length: 6 5/16 (160.3) A. Gskt.: 1 Included F. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal
BF1294-O 	Scania Gen Set Engines; Terex Crushers	Scania 1518512; SF-Filter SK3360	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 7 5/32 (181.8) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: 3 3/4-10 2B, Integral Post Seal
BF1296-O 	Doosan Equipment	Parker China Division WBF219B1; Sinotruk 13050733	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 6 13/32 (162.7) I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: B80 x 3.0 8A Metric Buttress
BF1297-O 	Mercedes-Benz European Trucks, Vans	Parker China Division WBF219H; Weichai Power 612630080088	Thread: 1-14 O.D.: 4 9/32 (108.7) Length: 9 3/32 (231.0) I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: B80 x 3.0 8A Metric Buttress, Integral Post Seal
BF1298-O 		Foton Lovol 1105111500002; CAMC 1125A86D-010; Parker China Division CX1014A	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 6 5/32 (156.4) A. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal
BF1299-O 		Yuchai Watyuan 612630080205	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 7 13/16 (198.4) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: 3 3/4-10 2B, Integral Post Seal

FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN PORT FOR BOWL

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF1345-O 	International Engines, Trucks	International 1618385-C91; Donaldson P550729	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 5 9/32 (134.1) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3-12 Related To: BF1345 (Drain Version) BF1345-SP (Sensor Port Version)
BF1346-O 	Ford, Freightliner, International, Sterling, Western Star Trucks; Racor Housings; Mercedes-Benz Engines	Racor S3226P; Donaldson P550554; Fleetguard FS19593	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 6 5/16 (160.3) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal Related To: BF1346 (Drain Version) BF1346-SP (Sensor Port Version)
BF1347-O 	Freightliner Chassis; Freightliner, International, Kenworth Trucks; Thomas Buses	Racor S3226T; ACDelco TP1348; Donaldson P551844; Fleetguard FS19933, FS19798; Wix 33813	Thread: 1-14 UNS-2B O.D.: 4 3/8 (111.1) Length: 6 7/32 (158.0) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10 UNS-2B, Integral Post Seal Related To: BF1347 (Drain Version)
BF1348-O 	Blue Bird Buses; Freightliner, Hino, Peterbilt Trucks; Racor 325 Fuel Assembly Series	Racor S3225P	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 5 3/16 (131.8) A. Gskt.: 1 Attached F. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal Related To: BF1348 (Drain Version) BF1348-SP (Sensor Port Version)
BF1355-O 	Thermo King Units; Volvo Trucks	Racor S3238P; Thermo King 11-9982; Volvo 85104856	Thread: 1 1/4-12 O.D.: 4 7/8 (123.8) Length: 6 5/16 (160.3) A. Gskt.: 1 Included F. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal Related To: BF1355 (Drain Version) BF1355-SP (Sensor Port Version)
BF1358-O 	Volvo Dump Trucks, Equipment	Volvo 11110474, 11110668	Thread: 1-14 O.D.: 4 13/32 (111.9) Length: 8 19/32 (218.3) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: 3 3/4-10, Integral Post Seal Related To: BF1358-SP (Sensor Port Version)
BF1360-O 	Blue Bird All-American, Vision Buses	Racor R90S; Donaldson P551854; Fleetguard FS20028	Thread: 1-14 O.D.: 4 9/32 (108.7) Length: 5 21/32 (143.7) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10 Buttress Related To: BF1360 (Drain Version) BF1360-SP (Sensor Port Version)
BF1366-O 	R.V.I., Volvo Trucks	Volvo 20998367; Donaldson P559628; Fleetguard FS19735	Thread: 1-14 O.D.: 3 21/32 (92.9) Length: 5 5/8 (142.9) F. Gskt.: 2 Included O-Ring: 1 Included	Contains: Bowl Thread: M80 x 2.5, Integral Post Seal
BF1379-O 	Idlebuster, Truck Gen Auxiliary Power Units (APUs); Next Generations Generators all with Kubota Engines	Ditch Witch 159047; Racor R12S, R12SUL; Fleetguard FS19628; Fram PS10975; Luber-finer LFF8676; Wix 33582, 533582	Thread: M18 x 1.5 O.D.: 3 1/32 (77.0) Length: 2 3/8 (60.2) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread 2 3/8-10 BSW Related To: BF1379 (Drain and Sensor Port Version) Notes: Inside-Out Flow Direction
BF1380-O 	Ampac P33/24 Compactor; Bandit Industries 2100SP Stump Grinder; Idlebuster Auxiliary Power Unit; Power Tech Auxiliary Power Units	Racor R12T	Thread: M18 x 1.5 O.D.: 3 (75.9) Length: 2 7/16 (62.3) A. Gskt.: 1 Included F. Gskt.: 1 Included O-Ring: 1 Included	Related To: BF1380 (Drain and Sensor Port Version) Notes: Inside-Out Flow Direction










FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN PORT FOR BOWL

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF1381-O 	Genie S100, S105, S120, S125 Lifts; Volvo VHD430 Trucks	Racor R12P; Donaldson P551768; Fleetguard FS19627	Thread: M18 x 1.5 O.D.: 3 3/32 (78.6) Length: 2 15/32 (62.7) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 2 3/8 Related To: BF1381 (Drain and Sensor Port Version)
BF1383-O 	DAF Engines, Trucks; Doosan, Terex Equipment	M.A.N. 5112501.7288, 5112503.0052; Daewoo K1006529; Parker China Division WBF219	Thread: 1-14 O.D.: 4 9/32 (108.7) Length: 9 3/32 (231.0) I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: B80 x 3.0 8A Metric Buttress
BF1386-O 	Mack, Volvo Engines, Trucks	Mack 21017305; Volvo 20879806	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 5 3/16 (131.8) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: M80 x 2.5, Integral Post Seal
BF1387-O 	Volvo Engines, Trucks	Volvo 20879812	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 6 5/16 (160.3) I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: M80 x 2.5, Integral Post Seal
BF1388-O 	R.V.I., Volvo Trucks	R.V.I. 7420851191; Volvo 20853583; Racor R60P-D-MAX; Fleetguard FS19895	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 5 1/8 (130.2) F. Gskt.: 1 Included I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal
BF1389-O 	Volvo Engines, Trucks	Volvo 20381204; Racor R45T; Donaldson P550746; Fleetguard FS19734	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 3 17/32 (89.7) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: 3 3/4-10 2B Buttress, Integral Post Seal
BF1390-O 	Volvo Trucks	Volvo 20450423; Racor R90T; Fleetguard FS19551	Thread: 1-14 O.D.: 4 11/32 (110.3) Length: 6 3/16 (157.2) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: 3 3/4-10 2B Buttress, Integral Post Seal
BF1391-O 	Mercedes-Benz Engines, Trucks	Mercedes-Benz 4771302, A0004771302; Fleetguard FS19914	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 8 21/32 (219.9) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal Related To: BF1359-SP (Sensor Port Version)
BF1395-O 	Freightliner Cascadia with Detroit Series 60 Engine	Alliance ABPN122R50421; Racor R120T; Donaldson P551075	Thread: 1-14 O.D.: 4 13/32 (111.9) Length: 8 19/32 (218.3) A. Gskt.: 1 Included F. Gskt.: 2 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal Related To: BF1265 (Drain Version) BF1395-SP (Sensor Port Version)
BF1398-O 	Volvo Trucks with D6B Engine	Volvo 20386080; Racor R25P; Fleetguard FS19704	Thread: 1-14 O.D.: 3 21/32 (92.9) Length: 5 5/8 (142.9) I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: M80 x 2.5, Integral Post Seal Notes: Inside-Out Flow Direction
BF5813-O 	Isuzu Trucks	Isuzu 8156189210; GM General Motors 156189210; Racor S3202T	Thread: 1-12 UNF-2B O.D.: 3 3/4 (95.3) Length: 7 13/32 (188.1) F. Gskt.: 2 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B Related To: BF5813 (Drain Version), BF5800 (No Drain Version)
BF7798-O 	Autocar, Ford, Freightliner, Peterbilt, Sterling, Western Star Trucks; Blue Bird, Thomas Buses	Alliance ABPN12232FRT03; Caterpillar 1986378; Racor S3201S	Thread: 1-14 O.D.: 3 5/8 (92.2) Length: 7 13/32 (188.2) F. Gskt.: 2 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8 - 10 UN-1B

FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN PORT FOR BOWL

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF7806-O 	Ford F750 with Caterpillar 3126, Cummins ISB 200 Engines	Ford Motor 5C4Z9N184AB; IHC (International Harvester) 2587803C1; Motorcraft FD4608; Parker PFF5527; Racor S6494	Thread: 1-14 O.D.: 3 21/32 (92.7) Length: 4 1/32 (102.4) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8 - 10 UN-1B Related To: BF7806 (Drain Version)
BF7968-O 	Racor B32012, B32014 Marine Fuel Systems	Racor S3214	Thread: 1-12 O.D.: 3 25/32 (96.0) Length: 4 1/32 (102.4) F. Gskt.: 2 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B Related To: BF7968 (No Drain Version)
BF9866-O 	John Deere Equipment	John Deere RE532952, RE539465	Thread: 7/8-14 O.D.: 4 3/8 (111.1) Length: 8 11/16 (220.7) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal
BF9867-O 	EvoBus Citaro Buses; Mercedes-Benz, Renault Trucks; Bomag Paving Equipment	Bomag 05825015; Renault 7420754418; Racor R160T-D-MAX	Thread: 1-14 O.D.: 4 13/32 (111.9) Length: 8 21/32 (219.9) A. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal
BF9871-O 	Freightliner, Sterling, Western Star Trucks	Alliance ABPN122BR90FRT10; Freightliner BR90FRT10, RAIBR90FRT10; Donaldson P551066	Thread: 1-14 O.D.: 4 5/16 (109.5) Length: 6 5/16 (160.3) A. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 3/4-10 2B Buttress, Integral Post Seal
BF9898-O 	Freightliner Cascadia, FLD, Business Class M2 Trucks	Alliance ABPN122R-50418; Fleetguard FS19593	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 6 5/16 (160.3) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal
BF9912-O 		Atlas Copco 2914809200; Fleetguard FS19775	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 3 15/32 (88.1) F. Gskt.: 1 Included I. Gskt.: 1 Included	Contains: Bowl Thread: 3 3/4-10 Buttress, Integral Post Seal
BF9921-O 	John Deere Industrial, Marine Engines	John Deere RE503676	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 8 21/32 (219.9) A. Gskt.: 1 Included F. Gskt.: 1 Included Grommet: 1 Attached	Contains: Bowl Thread: M95 x 2.5, Integral Post Seal, Pre-Fill Cup
BF9922-O 	Mercedes-Benz Latin America Buses, Trucks	Mercedes-Benz A3820927005; Racor R20P	Thread: 1-14 O.D.: 3 21/32 (92.9) Length: 4 1/8 (104.8) I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: M80 x 2.5, Integral Post Seal Related To: BF46021-O, BF46022-O (Micron Difference) Notes: Inside-Out Flow Direction
BF9923-O 	Atlas Copco, Bomag Equipment; Dynapac Rollers; Komatsu Excavators	Cummins 4941237; Komatsu 600-319-4110	Thread: M24 x 1.5 O.D.: 3 3/4 (95.3) Length: 5 1/4 (133.4) I. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 1 1/4-10

FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN PORT FOR BOWL

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF9925-O 		Racor S6464; Donaldson P551034; Fleetguard FS19538	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 6 5/16 (160.3) F. Gskt.: 2 Included	Contains: Bowl Thread: M95 x 2.5
BF46016-O 	Freightliner Trucks; Racor Fuel Systems	Freightliner ABPN122R50551	Thread: 1-14 O.D.: 4 11/32 (110.3) Length: 6 1/8 (155.6) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10 Buttress, Integral Post Seal
BF46017-O 	Bobcat Compressors; Doosan G20 Portable Generators; Ingersoll Rand Compressors	Ingersoll Rand 54525530	Thread: 1-12 O.D.: 3 25/32 (96.0) Length: 3 1/4 (82.6) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B
BF46018-O 	International, Navistar Trucks with Maxxforce Engine	International 2602549C1	Thread: 1-14 O.D.: 4 1/4 (108.8) Length: 8 17/32 (216.7) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10UNS-2B, Integral Post Seal Related To: BF1281 (Drain Version)
BF46019-O 	Racor 215R Fuel Assembly	Racor R15S	Thread: 1-14 O.D.: 3 13/16 (96.8) Length: 3 9/32 (83.3) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B
BF46020-O 	Racor 215R Fuel Assembly	Racor R15T	Thread: 1-14 O.D.: 3 13/16 (96.8) Length: 3 9/32 (83.3) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B
BF46021-O 	Racor 230R Fuel Assembly Series	Racor R20S	Thread: 1-14 O.D.: 3 11/16 (93.7) Length: 4 1/16 (103.2) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B Related To: BF9922-O, BF46022-O (Micron Difference)
BF46022-O 	Racor 230R Fuel Assembly	Racor R20T	Thread: 1-14 O.D.: 3 11/16 (93.7) Length: 4 1/32 (102.4) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B Related To: BF9922-O, BF46021-O (Micron Difference)
BF46023-O 	Racor 220R Fuel Assembly (Old Version)	Racor R24P	Thread: 1-14 O.D.: 3 3/4 (95.3) Length: 3 9/16 (90.5) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 1 1/4-10
BF46024-O 	Racor 220R MAM Fuel Assembly	Racor R24T	Thread: 1-14 O.D.: 3 3/4 (95.3) Length: 3 9/16 (90.5) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 1 1/4-10
BF46025-O 	Racor R245R Fuel Assembly	Racor R25T	Thread: 1-14 O.D.: 3 3/4 (95.3) Length: 5 17/32 (140.5) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B
BF46026-O 	Racor 225 Fuel Assembly Series	Racor R26T; Donaldson P550088; Fleetguard FS1234	Thread: 1-14 O.D.: 3 3/4 (95.3) Length: 4 21/32 (118.3) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 1 1/4-10



FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN PORT FOR BOWL

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF46027-O 	Racor 400, 600 Fuel Assembly Series	Racor R45S	Thread: 1-14 O.D.: 4 3/8 (111.1) Length: 3 1/2 (88.9) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10 ANS Buttress, Integral Post Seal
BF46028-O 	Racor 320R-RAC-02 Mounting Base; Marine Engines	Racor S3227	Thread: 1-14 O.D.: 4 (101.6) Length: 4 1/16 (103.2) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B
BF46029-O 	Racor Marine Applications	Racor S3228UL	Thread: 1-14 O.D.: 3 25/32 (96.0) Length: 4 1/32 (102.4) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/4-10, Integral Post Seal
BF46030-O 	Racor 660R-RAC, 3120R-RAC Fuel Assembly Series	Racor S3232	Thread: 1-14 O.D.: 3 25/32 (96.0) Length: 5 1/2 (139.7) F. Gskt.: 2 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 3/4-10 UN-1B Related To: BF1350-SP (Sensor Port Version)
BF46083-O 	Scania Trucks; Doosan Dump Trucks; JCB (J.C. Bamford) Generators	Scania 1393640	Thread: 1-14 O.D.: 4 1/2 (114.3) Length: 6 3/16 (157.2) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10 Buttress, Integral Post Seal Related To: BF46072 (Bowl Version), BF1329 (Drain Version), BF1329-SP (SP Thd. 9/16-18), BF1339-SP (SP Thd. 1/2-20)
BF46098-O 	Freightliner Century Class, Cargo FC80, Cascadia Trucks	Alliance ABP/N122-R50419; Donaldson P551034, P551857; Fleetguard FS19798; ACDelco TP1348;	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 6 9/32 (159.5) F. Gskt.: 2 Included Grommets: 1 Attached	Contains: Bowl Thread: 3 3/4-10 UNS B, Integral Post Seal Related To: BF1373-SP (Sensor Port Version)
BF46099-O 	John Deere Equipment	John Deere AT365869; Racor R51401; Donaldson P551858; Fleetguard FS19754; Wix 33986	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 8 19/32 (218.3) F. Gskt.: 2 Included Grommets: 1 Attached	Contains: Bowl Thread: 3 3/4-10 UNS 2B, Integral Post Seal
BF46100-O 	John Deere Equipment	John Deere AT365870; Racor R51402; Donaldson P551034; Fleetguard FS19538	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 6 7/32 (158.0) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10 UNS B, Integral Post Seal
BF46101-O 	Volvo-Penta Marine Diesel Engines	Volvo 3817517; Racor R120S-HD; Fleetguard FS19896	Thread: 1-12 O.D.: 4 11/32 (110.3) Length: 8 1/2 (215.9) F. Gskt.: 2 Included	Contains: Female Bowl Thread: 3 3/4
BF46105-O 	Mercedes-Benz European, South American Trucks	Mercedes-Benz A0004771702, 4771702; Racor R160P, R90DMER03; Fleetguard FS19737	Thread: 1-14 UNS O.D.: 4 11/32 (110.3) Length: 8 1/2 (215.9) F. Gskt.: 2 Included	Contains: Female Bowl Thread: 3 3/4
BF46109-O 	Mercedes-Benz Latin America Buses, South America Trucks, Buses, Vans	Mercedes-Benz A3844777015, A9794770015, A9794770015AZ, 3844777015, 9794770015, 9794770015AZ; Racor R120MB, R12030MB	Thread: 1-12 O.D.: 4 17/32 (115.3) Length: 6 9/16 (166.9) A. Gskt.: 1 Included O-Ring: 1 Included	Contains: Male Bowl Thread: 3 3/4

FUEL/WATER SEPARATOR SPIN-ONS WITH OPEN PORT FOR BOWL

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF46123-O 	Mercedes-Benz Buses, Trucks	Ford BHOX9N074AA, T22VA, 9C459C340AB; Mercedes-Benz A9584770115, 9584770115; Racor R12010MBAQII	Thread: 1-12 O.D.: 4 17/32 (115.3) Length: 7 5/32 (181.9) A. Gskt.: 1 Included O-Ring: 1 Included	Contains: Male Bowl Thread: 3 3/4
BF46134-O 	Volvo European FH Series Trucks	Racor R90P-D MAX; Volvo 21005832, 21380490, 20782330; Donaldson P954895; Fleetguard FS20053	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 7 5/8 (194.1) A. Gskt.: 1 Included F. Gskt.: 1 Included	Contains: Bowl Thread: 3 3/4-10 Buttress
BF46147-O 	Freightliner FS-65 Buses; Ingersoll Rand Equipment	Case 84211170; Racor R60P; Volvo 13224043, 13224043V; Ingersoll Rand 13224043, 13224043IR	Thread: 1-14 UNS-2B O.D.: 4 1/4 (108.0) Length: 5 3/32 (129.4) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10 ANS Buttress Related To: BF1329 (Drain Version), BF1329-SP (SP Thd. 9/16-18), BF1339-SP (SP Thd. 1/2-20)
BF46150-O 	Case-International, New Holland Harvesters, Tractors	Case 84423586; Racor S3207P	Thread: 1 1/4-12 O.D.: 4 27/32 (122.9) Length: 9 29/32 (251.5) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10
BF46162-O 	Racor 215R Fuel Filter Assembly	Northern Lights/Lugger 2450014; Racor R15P	Thread: 1-14 O.D.: 3 5/16 (95.1) Length: 3 15/16 (83.6) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UN-1B
BF46164-O 	Racor 120A, 120B Fuel Filter Assemblies	Racor R13P	Thread: M18 x 1.5 O.D.: 3 (76.2) Length: 3 31/32 (100.6) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 2 3/8-10 Whitworth
BF46169-O 	Blue Bird All American, Vision School Buses; International 4300, 4300LP, 4400, 7400, 7500, HV507, HV607 Trucks	Blue Bird 10054676, R34000BB01; IHC (International Harvester) 4080114C1, 4080114C2	Thread: 1-14 O.D.: 4 7/32 (107.4) Length: 6 1/8 (155.3) F. Gskt.: 2 Included	Contains: Bowl Thread: 3 3/4-10 ANS Buttress
BF46173-O 	Volvo North America Trucks with Cummins ISX Engines	Racor S3238T; Volvo 85121709	Thread: 1 1/4-12 O.D.: 4 27/32 (122.7) Length: 6 9/32 (159.7) F. Gskt.: 2 Included	Contains: Bowl Thread: 3-3/4-10 UNS-2B SPECIAL
BF46181-O 	International, Mack Trucks	IHC (International Harvester) 2514003C1; Racor R33838	Thread: 1-14 O.D.: 4 1/4 (108.0) Length: 5 21/32 (143.5) F. Gskt.: 2 Included	Contains: Bowl Thread 3 3/4-10
BF46182-O 	Mack, Volvo North America Trucks	Mack 22094987; Volvo 21764964	Thread: 1-14 O.D.: 4 7/32 (106.9) Length: 5 1/32 (127.5) F. Gskt.: 1 Included O-Ring: 1 Included	Contains: Bowl Thread: 3 1/8-10 UNS B,

FUEL/WATER SEPARATOR WITH BOWL AND DRAIN

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
BF46071 	Mercedes-Benz Trucks	Mann & Hummel WK1060	Thread: 1-12 O.D.: 4 1/32 (102.4) Length: 11 (279.4) I. Gskt.: 1 Included	
BF46072 	Volvo Construction Equipment	Mann & Hummel WK1060/1; Donaldson P502457, P551067, P551361	Thread: 1-12 O.D.: 4 1/32 (102.4) Length: 11 (279.4) I. Gskt.: 1 Included	Related To: BF46083-O (Open Port Version); BF1339-SP (SP Thd. 1/2-20); BF1329-SP (SP Thd. 9/16-18); BF1329 (Drain Version)

CROSS-REFERENCE GUIDE

BALDWIN	DONALDSON	FLEETGUARD	FRAM	LUBER-FINER	WIX
BF791-O	-	-	-	-	33769
BF1204-O	P551845	FS1234	PS6643	LFF8061	33446
BF1222-O	P553375	FS1281	PS6554	LFF5824	33217
BF1223-O	P551852	FS19687	PS8187	LFF8063	33231
BF1249-O	P551864	FS1242	PS8048	-	33242
BF1278-O	-	FS20080	-	LFF9012	-
BF1281-O	P551859	FS19754	-	-	33774
BF1282-O	-	FS1241	PS11069	LFF8065	33421
BF1283-O	P550175	FS1071	-	LFF8707	-
BF1287-O	-	FS20036	-	-	-
BF1288-O	P550937	-	-	LFF5357	33942
BF1292-O	-	FS19950	-	-	-
BF1294-O	-	-	-	-	-
BF1296-O	-	FS19907	-	-	WF10310
BF1297-O	-	FS20071	-	-	-
BF1298-O	-	-	-	-	-
BF1299-O	-	-	-	-	-
BF1345-O	P550729	FS19547	PS8186	LFF3579	33232
BF1346-O	P553226	FS19593	PS9794	LFF5850	33812
BF1347-O	P553227	FS19798	PS11143	LFF5851	33813
BF1348-O	P551844	FS19521	PS7713	LFF5849	33630
BF1355-O	-	FS19799	PS9707	LFF9982	33938
BF1358-O	P551859	FS19753	PS10971	LFF9753	33782
BF1360-O	P551854	FS20028	-	LFF8063	33788
BF1366-O	P551843	FS19735	-	LFF3293	WF10210
BF1379-O	-	FS19628	PS10975	LFF8676	33582
BF1380-O	-	FS19802	PS11281	LFF8678	33583
BF1381-O	P551768	FS19627	PS10973	LFF8677	33584
BF1383-O	P550778	FS19769	-	LFF9769	33713
BF1386-O	P551838	FS19966	PS10678	LFF3358	33995
BF1387-O	-	FS19920	-	-	WF10011
BF1388-O	-	FS19895	-	-	WF10010
BF1389-O	P551849	FS19734	-	-	33440
BF1390-O	P551855	FS19551	PS9915	-	-
BF1391-O	-	FS19914	-	LFF9737	33683
BF1395-O	P551858	FS19591	PS9263	LFF8707	33780
BF1398-O	-	FS19704	-	-	33441
BF5813-O	P551840	FS19513	PS6830	LFF9002	33442
BF7798-O	P558020	FS1222	PS3712	LFF9013	33783
BF7806-O	P550553	FS19904	PS9111	LFF5089	33736
BF7968-O	-	-	-	-	33770
BF9866-O	P552952	FS1096	-	LFF6964	33969
BF9867-O	P955606	FS19949	-	-	-
BF9871-O	P551066	-	-	LFF8957	-
BF9898-O	P551856	FS19593	-	LFF5849	-
BF9912-O	P551850	FS19775	-	-	33755
BF9921-O	-	-	-	-	33986
BF9922-O	P551820	FS19996	PS10978	-	33614
BF9923-O	P502566	FS19805	-	-	WF10163
BF9925-O	P551034	FS19538	-	-	33047

CROSS-REFERENCE GUIDE CONT.

BALDWIN	DONALDSON	FLEETGUARD	FRAM	LUBER-FINER	WIX
BF46016-O	-	FS20095	-	-	WF10012
BF46017-O	-	FS19964	-	-	33730
BF46018-O	P551839	FS20040	-	LFF7660	WF10006
BF46019-O	-	-	-	-	33433
BF46020-O	-	-	-	-	33435
BF46021-O	P551822	-	PS10980	-	33776
BF46022-O	P551821	-	-	-	33432
BF46023-O	-	-	-	-	33447
BF46024-O	P551744	-	-	-	33445
BF46025-O	-	FS19778	PS9257	-	33771
BF46026-O	P551846	FS1234	-	-	33443
BF46027-O	P551848	FS1084	-	-	33773
BF46028-O	-	-	-	-	33757
BF46029-O	-	-	-	-	33772
BF46030-O	-	-	-	-	33746
BF46083-O	P551856	FS19532	PS7716	LFF5766	33838
BF46098-O	P551857	FS19798	-	LFF5851	WF10059
BF46099-O	-	FS19754	-	-	33986
BF46100-O	P551034	FS20127	-	-	WF10110
BF46101-O	-	FS19896	-	-	33683
BF46105-O	-	FS19737	PS10701	-	-
BF46109-O	P551086	FS20041	-	LFF5778	WF1060
BF46123-O	P551086	FS1106	-	-	WF1060
BF46134-O	P954895	FS20053	-	-	-
BF46147-O	P551853	FS1287	-	LFF5766	WF10253
BF46150-O	P553200	FS20115	-	-	WF10214
BF46162-O	-	FS19824	-	-	WF10097
BF46164-O	-	-	-	-	-
BF46169-O	-	-	-	-	-
BF46173-O	-	-	-	-	-
BF46181-O	-	-	-	-	-
BF46182-O	-	FS20132	-	-	-



800.822.5394 | baldwinfilters.com

Designed and manufactured in the USA.

Form 583-SM (R 1/21) © 2021 Baldwin Filters, a Parker Hannifin Company

Printed in the U.S.A.

⚠ WARNING: These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol-A, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.