ENGINEERING BULLETIN 17-2

April 4, 2017

Installation Instructions for CA30103 and CA30104

Baldwin Filters recently introduced the CA30103 and CA30104 Channel Flow EXO air elements. When installing the CA30103 or CA30104 element in the housing, the element may appear to be installed properly.

BALDWII

FILTER5

1.

2.

3.

However, it is important that you follow the steps below to guarantee the element is in the correct position and the housing lid is attached and sealed properly.

Following the Steps Below:

- 1. enkoure proper installation, first push down on the inlet side of the element.
- 2. Next, push down on the opposite side of the element until you hear the element snap into place.
- Attach the housing lid and tighten all bolts. (Lid should be tightened to torque specified on lid)


PLEASE NOTE:

If the element is not secured correctly, the housing lid will not close properly.

CORRECT

INCORRECT





If you have further questions, please call our Service Engineering Team at (308) 237-9729.



WARNING: These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol-A, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.